

TOP SECRET

IN 8519F

OPS 10 60

TOP SECRET 061015Z CITE [REDACTED]

25X1A

IMMEDIATE [REDACTED] INFO [REDACTED]

25X1A
25X1A
25X1A

A. EX6843

B. CAMERA ON & OFF REPORT

C. TYPE 1:

	(1)	(2)	(3)	(4)	(5)
-5	011659	2116	12325	714	
-3	011721	2114	12324	728	
-1	011711	2114	12323	731	
0001	015519	1247	10747	787	
0003	NR	NK	NK	NR	
0005	015531	1244	10742	788	
0007	015537	1242	10739	788	
767	022443	2009	10145	657	
769	022449	2007	10144	643	
771	022455	2004	10142	629	
773	031125	1714	NK	88	
775	NR	NK	NK	NR	
777	NR	NK	NK	NK	
1561	NR	NR	NR	NR	
1563	034215	1708	11016	747	
1565	034222	1709	11019	748	

D. CAMERA CAGED INDICATOR APPEARS PERIODICALLY THROUGHOUT MISSION.

CLOCK APPEARS IN IMAGE AREA PERIODICALLY THROUGHOUT MISSION.

TOP SECRET TOR: 061051Z JAN 68

TOP SECRET

Approved For Release 2002/06/13 : CIA-RDP69B00041R001500030014-5

25X1A

Next 6 Page(s) In Document Exempt

Approved For Release 2002/06/13 : CIA-RDP69B00041R001500030014-5

TOP SECRET

POSTED

IN 85P47

OPS 1-1603

TOP SECRET 052232Z CITE

IMMEDIATE


25X1A

25X1A
25X1A

- A. BX 6843
- B. INS TAPE EVALUATION REPORT
- C. INS 61F
- D. 74/1123 B
- E. 1. SATISFACTORY
2. SATISFACTORY
3. SATISFACTORY
4. SATISFACTORY
5. SATISFACTORY
6. SATISFACTORY
7. BETWEEN ELAPSED TIMES 13096 AND 13145, 13169, AND 13192, THE TENTHS DIGIT IN THE ROLL RECORDS WAS MISSING.
BETWEEN ELAPSED TIMES 13247 AND 13268 THERE WERE TWO LINES WHERE THE TENTHS DIGIT IN THE ROLL RECORD WAS MISSING.
8. SATISFACTORY
9. SATISFACTORY
10. SATISFACTORY
- F. TAPE APPEARS GENERALLY SATISFACTORY. TAPE EVALUATION PERTAINS TO CAMERA OPERATION ONLY.

TOP SECRET TOR:
052243Z JAN 68

TOP SECRET



CLASSIFIED MESSAGE

DATE

TOP SECRET

TO :

FROM :

ACTION:

INFO :

IN 85245

OPS 1-18 03

ROUTING	
1	9
2	10
3	11
4	12
5	13
6	14
7	15
8	16

POST 10

TO

INFO

CITE

25X1A

TOP SECRET 052145Z CITE

25X1A

IMMEDIATE

OXCART

[REDACTED]

- A. BX6843
- B. FLASH REPORT AFTER PROCESSING
- C. TYPE I
- D. C
- E. THE FILM ARRIVED IN GOOD PHYSICAL CONDITION WITH NORMAL EXPOSURE, MEDIUM CONTRAST, AND GOOD RESOLUTION. DATA RECORDING WAS OPERATIONAL IN FWD POSITION, AND INTERMITTANT IN THE AFT POSITION WITH 75 TO 100 CHAMBERS ABSENT. CAMERA STARTUP AND SHUTDOWN NORMAL WITH RECYCLE OCCURRING THROUGHOUT 40 FRAMES, 50 0/0 INTO MISSION. DATA CHAMBERS WERE SLANTED APPROXIMATELY 6 DEGREES TO THE LEFT OF BIAS CAUSING SOME DATA CHAMBERS TO ENTER IMAGERY UP TO 1/16". TWO MINUS DENSITY LINES, 1/16" APART AND 3 3/4" FROM TRAILING EDGE AND ONE MINUS DENSITY LINE 1 1/4" FROM LEADING

TOP SECRET

GROUP 1
EXCLUDED FROM AUTO-
REFILE PROCESSING
AND DECLASSIFICATION

25X1A IN 85845 T O P S E C R E T PAGE 2

EDGE OCCURRING ON ALL FWD GRAMES. A MINUS DENSITY LINE WAS NOTED 2 1/2 INCHES FROM LEADING EDGE ON ALL AFT FRAMES. HEAVY YELLOW DISCOLORATION SIMILAR TO EX6842 PRESENT IN THE FILM. DISCOLORATION WAS NOT NOTED ON IDENT MATERIAL PRESPLICED ONTO MISSION MATERIAL. ALSO PRESENT WAS AN ORANGE PEEL EFFECT ON THE FILM.

T O P S E C R E T TOR: 052229Z JAN 68

T O P S E C R E T